


710 Vertical Machining Centre Siting Requirements




Shown with optional Swarf Conveyor

Machine Dimensions


| | |
|-------------------------|--------|
| Minimum Width Required | 2100mm |
| Minimum Depth Required | 2240mm |
| Minimum Height Required | 2600mm |

Power & Air Requirements

| | |
|------------------|--|
| Single Phase | Not Required |
| Three Phase | 415v |
| Neutral Required | Not Required |
| Main Fuse | 60amp / Phase |
| Air Requirement | 220 L/Min @ 6 bar |
| Air Fitting | 1/4" PCL-BSP Push Fitting, male on machine, female required on hose. (As Pictured) |



Hose Fitting



Machine Fitting