


Machine Dimensions


Minimum Width Required	3650mm *including swarf conveyor
Minimum Depth Required	2370mm
Minimum Height Required	3250mm

Power & Air Requirements

Single Phase	Not Required
Three Phase	415v
Neutral Required	Not Required
Main Fuse	80amp / Phase
Air Requirement	220 L/Min @ 6 bar
Air Fitting	1/4" PCL-BSP Push Fitting, male on machine, female required on hose. (As Pictured)



Hose Fitting



Machine Fitting